	Туре	L #	Hits	Search Text	DBs
1	BRS	L1	O	(space adj2 charge or charges)	US- PGPUB; USPAT
2	BRS	L2	0	(chaco adi? (charge or charges))	US- PGPUB; USPAT
3	BRS	L3	O	(space adj2 (charge or charges))	US- PGPUB; USPAT
4	BRS	L4	0	(charge or charges) near20 (crytal	US- PGPUB; USPAT
5	BRS	L5	0	(charge or charges) same (crytal	US- PGPUB; USPAT
6	BRS	L6	O	(charge or charges) same (crytal	US- PGPUB; USPAT
7	BRS	L7	o	ferrolectric same (crytal adj2 defect)	US- PGPUB; USPAT
8	BRS	L8	0	ferrolectric same (crytal adj2 defect)	USOCR; EPO; JPO; DERWE NT; IBM_TD B

	Туре	L #	Hits	Search Text	DBs
9	BRS	L9	1	(crytal adj2 defect)	USOCR; EPO; JPO; DERWE NT; IBM_TD B
10	BRS	L10	1	crytal adj2 (defects or defect)	USOCR; EPO; JPO; DERWE NT; IBM_TD B
11	BRS	L11	3	crytal adj2 (defects or defect)	US- PGPUB; USPAT
12	BRS	L12	2024	(charge or charges) near5 (implanting or implantation or implant or implanted)	US- PGPUB; USPAT
13	BRS	L13	22057	(impurity or impurities) near5 (implanting or implantation or implant or implanted)	US- PGPUB; USPAT
14	BRS	L14	358	13 near15 (charges or charge)	US- PGPUB; USPAT
15	BRS	L15	0	14 near15 ferrolectric	US- PGPUB; USPAT
16	BRS	L16	o	14 near15 ferroelectric	US- PGPUB; USPAT

	Type	L #	Hits	Search Text	DBs
17	BRS	L17	577	(defects or defect) near25 ferroelectric	US- PGPUB; USPAT
18	BRS	L18	93	17 same (charges or charge)	US- PGPUB; USPAT
19	BRS	L19	0	13 same 18	US- PGPUB; USPAT
20	BRS	L20	7	13 and 18	US- PGPUB; USPAT
21	BRS	L21	1058	(defects or defect) near10 (crystallization or crystallize or crystallizing)	US- PGPUB; USPAT
22	BRS	L22	27	21 near25 ferroelectric	US- PGPUB; USPAT
23	BRS	L23	37733	(opposite or (negative near5 positive)) near6 (charges or charge)	US- PGPUB; USPAT
24	BRS	L24	129	23 near10 ferroelectric	US- PGPUB; USPAT
25	BRS	L25	246981	upper near5 lower near5 (regions or region or portions or portion or section)	US- PGPUB; USPAT
26	BRS	L26	81	23 near20 24	US- PGPUB; USPAT
27	BRS	L27	6	23 near20 25	US- PGPUB; USPAT

	Туре	L #	Hits	Search Text	DBs
28	BRS	L28	o	24 same 25	US- PGPUB; USPAT
29	BRS	L29	4399	ferroelectric adj2 (layer or film)	US- PGPUB; USPAT
30	BRS	L30	61	23 same 29	US- PGPUB; USPAT
31	BRS	L31	o	25 same 30	US- PGPUB; USPAT
32	BRS	L32	36	23 near20 29	US- PGPUB; USPAT
33	BRS	L33	154	(multiple or multilayer or multi) near5 (ferroelectric adj2 (layer or film or layers or films))	US- PGPUB; USPAT
34	BRS	L34	490	13 near15 (defect or defects)	US- PGPUB; USPAT
35	BRS	L35	310	13 near10 (charges or charge)	US- PGPUB; USPAT
36	BRS	L36	17	34 near15 (charges or charge)	US- PGPUB; USPAT
37	BRS	L37	19558	(impurity or impurities) near3 (implanting or implantation or implant or implanted)	US- PGPUB; USPAT
38	BRS	L38	267	37 near10 (charges or charge)	US- PGPUB; USPAT

	Туре	L #	Hits	Search Text	DBs
39	BRS	L39	0	29 same 38	US- PGPUB; USPAT
40	BRS	L40	1	29 and 38	US- PGPUB; USPAT
41	BRS	L41	11339	(impurity or impurities) near3 (implanting or implantation or implant or implanted)	USOCR; EPO; JPO; DERWE NT; IBM_TD B
42	BRS	L42	0	41 near10 (charges or charge or defects or defect)	US- PGPUB; USPAT
43	BRS	L43	252	41 near10 (charges or charge or defects or defect)	USOCR; EPO; JPO; DERWE NT; IBM_TD B
44	BRS	L44	0	29 and 43	USOCR; EPO; JPO; DERWE NT; IBM_TD B

	Туре	L #	Hits	Search Text	DBs
45	BRS	L45	346	41 near20 (charges or charge or defects or defect)	USOCR; EPO; JPO; DERWE NT; IBM_TD B
46	BRS	L46	0	29 and 45	USOCR; EPO; JPO; DERWE NT; IBM_TD B
47	BRS	L47	151	41 near5 (charges or charge or defects or defect)	USOCR; EPO; JPO; DERWE NT; IBM_TD B
48	BRS	L48	84	41 near5 (defects or defect)	USOCR; EPO; JPO; DERWE NT; IBM_TD B
49	BRS	L49	257	29 near3 "pb"	US- PGPUB; USPAT
50	BRS	L50	O	49 near10 (benefits or benefit or advantages or advantage or reason or reasons or why)	US- PGPUB; USPAT

	Type	L #	Hits	Search Text	DBs
51	BRS	L51	9	49 same (benefits or benefit or advantages or advantage or reason or reasons or why)	US- PGPUB; USPAT